



Department of Environmental Protection

Jeb Bush Governor Twin Towers Building 2600 Blair Stone Road Tallahassee, Florida 32399-2400 David B. Struhs Secretary

March 5, 2001

Ms. Beverly Washington
Department of the Navy, Petroleum Program
Southern Division - Naval Facilities Engineering Command
PO Box 190010
2155 Eagle Drive
North Charleston, SC 29419-9010

file: 351sar1.doc

RE: Site Assessment Report Tank Site 351, Naval Station Mayport, Mayport, FL

Dear Ms. Washington:

I have reviewed the above document dated February 14, 2001 (received February 14, 2001). Information furnished in the report indicates that one well (351-MW05) sample contained total xylenes above the Natural Attenuation Default Concentration. This well has been sampled only once. I suggest that the well be resampled for volatile and semivolatile petroleum constituents. Following that, please prepare a SAR Addendum with recommendations for the site. As we have discussed, if the total xylenes are 200 ug/L or less, please prepare a Monitoring for Natural Attenuation Plan according to Chapter 62-770.690, F.A.C.

If further clarification is required or if you have any questions, please contact me at 850-921-4230.

Herry

James H. Cason, P.G.

Remedial Project Manager

CC: Jan Bouvier, NAVSTA Mayport
Mark Peterson, TetraTech, Jacksonville

Mark Peterson, TetraTech, Jacksonvill

ijc**}}{**esn**£5N**/

MAR 2 0 2001

TETRA TECH NUS
JACKSONVILLE FL

"Protect, Conserve and Manage Florida's Environment and Natural Resources"